



VICTORIAN HANG GLIDING AND PARAGLIDING ASSOCIATION

Site Assessment Report (ref. Parks Vic License, Schedule 1, para 3.2)

SITE

Site Name	Mt. Buffalo		Date of inspection	16 / 02 / 2019	
Site Inspected by	Gabriel Toniolo	HGFA no. / Position	34617	Signature	<i>Gabriel Toniolo</i>
Report Reviewed by		HGFA no. / Position		Signature	<i>S. H. Norman</i>

RESULTS OF ASSESSMENT

Assessed as satisfactory at date of inspection?	Comments
Yes	Site has had no signs of deterioration. Ramp is in sound condition on both its surface and footings and structure. All signs are clear and not "tagged". The area shows no signs of vandalism and no rubbish was visible.

NOTES/ACTIONS

Items	Comments
- N/A	Nothing Required.

CHECKLIST AID

CHECKLIST ITEMS	STATUS (tick appropriate box)			Describe action required (if any)
	Not Applicable	Good	Needs attention	
Site Guide contents for site		Accurate		
Access track condition		Good		
Emergency Marker Post	None		Desirable	Whilst no emergency marker is present. Launch location is well sign posted. Emergency LZ could / should have a marker.
Site signage		Very Good		
Fencing/Barriers		Public no access sign		
Set up area		Natural granite rock		It would be advantageous for some of the new vegetation growth in the set up area to be pruned and trimmed.
Launch area		Very Good		
Launch structure		Excellent		
Vegetation	None on launch		Set up area	Set up area could use a pruning.
Clear of rubbish		Good		
Other		Good		No rubbish visible, all in excellent appearance.

PLANS FOR MANAGEMENT OF SITE

Emergency Markers are desirable and should be organized along with the other NE Vic sites yet to have markers.
--