



VICTORIAN HANG GLIDING AND PARAGLIDING ASSOCIATION

Site Assessment Report (ref. Parks Vic License, Schedule 1, para 3.2)

SITE

Site Name	Bells Beach - South Side		Date of inspection	9 / April / 2019	
Site Inspected by	Rob van der Klooster	HGFA no. / Position	33153 VHPA president	Signature	<i>Rob van der Klooster</i>
Report Reviewed by	Peter Hannah	HGFA no. / Position	34760 Dynasoarers President	Signature	<i>Peter Hannah</i>

RESULTS OF ASSESSMENT

Assessed as satisfactory at date of Inspection?	Comments
- .Yes	-

NOTES/ACTIONS

Items	Comments
-	-

CHECKLIST AID

CHECKLIST ITEMS	STATUS (tick appropriate box)			Describe action required (if any)
	Not Applicable	Good	Needs attention	
Site Guide contents for site		✓		
Access track condition		✓		
Emergency Marker Post	✓			
Site signage		✓		See pictures
Fencing/Barriers		✓		See first picture
Set up area		✓		
Launch area		✓		See picture
Launch structure		✓		
Vegetation		✓		
Clear of rubbish		✓		
Other				

PLANS FOR MANAGEMENT OF SITE

<p>Would like to extend Astroturf over North Eastern path to stop path material running onto Launch/Setup Area and delineate the 'No Spectator area (see last picture)</p>
--



